



A.) Take off the clips on the end cap.






B.) Push the lens to one end.






C.) Pull up the lens.

Mechanical Connection






Note: Please screw the connection plate inside the fixture after you disassemble the lens.

Sensor Wiring:




Note: Pull up the on the clips to adjust the wiring. Avoid dropping the unit after the surface has been mounted.




Note: Keep the clips back on the lens and end cap. Next, remove the label on the lens.


■ Wiring Diagram



■ B.) Remove cover to install Motion Sensor



■ C.) Morris CAT# 71729A Motion Sensor Kit



Wiring for adding CAT# 71729A Sensor

