



NOTE:
1. THIS STRIKE IS NOT HANDED. LATCH BOLT OPENING IS OFFSET IN THE SAME DIRECTION FOR "LHR" AND "RHR" APPLICATION.

283 Strike Application for 98/9947-WDC, 33/3547-WDC, & 33/3547A-WDC

VON DUPRIN®

NOTES: SEE MASTER SHEET #10001 FOR SUGGESTED REINFORCING

TEMPLATE NUMBER: W30230_a

DATE: 05-29-13