

Upload/Download PC Data 1 5 8 *

Print Clock Settings 1 5 7 *

Print User Code List 1 5 6 *

Print Audit Trail 1 5 5 *

Timed Passage Mode 1 4 7 1 [] XXX Hours *

Quick Function List



PDL5300



DL & PDL5300



DL5300

Quick-Reference Guide to Programming Codes and Functions

This is only a summary of Programming Codes and Functions. Refer to Programming instructions WI1622 & WI1672 for more information. **OI351 6/08**

Quick Function List

Entering Program Mode

[_ _ _ _ _] 
Master Code

Change Master

  1  [_ _ _ _ _]  [_ _ _ _ _]  *
New Master Code Confirm New Master Code

Add/Delete User

  2  [_ _]  [_ _ _ _ _]  *
User Number New User Code

Disable User

  3  [_ _]  *
User Number

Enable User

  4  [_ _]  *
User Number

Fold on Line

Set Date

  3  8  [_ _ _ _ _]  *
Date, MM DD YY

Set Time

  3  9  [_ _ _]  *
Time, HH MM 24 Hour Format

Set Day

  4  0  [_]  *
Day (1 – 7), Sun =1

Enable Passage Mode

  4  5  *

Disable Passage Mode

  4  6  *

Exit Program Mode

Hold down any key for 5 seconds