

## **US** Troubleshooting Guide Verti 840

### Products

VERTI 840

---

The Verti wall cabinet lift unit is designed and tested to achieve optimum operation reliability and long life, provided that the operation, maintenance and inspections are carried out in accordance with the prescribed instructions. If in spite of this a fault appears you can get guidance about what to do according to the faultfinding list below.

Remove the load from the cabinet before fault finding and repair work is carried out. Fault finding, service and repair work shall made by competent persons only.

If any problem remains after you have taken actions in accordance with the list below you must contact a competent technician or you supplier

Symptom	Action
<p><b>The shelves do not move when a control signal is given</b></p>	<p>Check that the safety trip plate is not actuated.</p> <p>If the shelves still do not move contact an authorized technician and/or your supplier.</p> <p>This shall as first action, after above check points, check that all cables are connected and undamaged.</p>