





# ART. 841HB108


## AP1003

C	· 2 x	Y	· 2 x	L	· 2 x	M	· 4 x
				6x16 plastic		6x18 metal	
N	· 4 x	X	· 2 x	P	· 2 x	Q	
TB 6x12		TB 6x16		TPS 6x15		+ 4x20	
G	· 2 x	U					
Ø16x20		· 2 x					
		Ø16x6					



## AP1004

O	· 24 x	P	· 18 x
			
TP 6x50		TPS 6x15	



## AP1010

R	· 42 x
	
compass 6 MA	

## AP1021

AA	· 4 x	BB	· 4 x	CC	· 4 x
				rubber pad	

## AP1000

S	· 2 x	V	· 2 x	T1	· 3 x
magnet					
		TS 3.5x16		TS 4x35	